2/6/2015









<u>The Past Week</u>

- Roofing
- Elevator install
- Metal siding at courtyard
- Exterior framing and sheeting level 12
- Weather barrier levels 11 and 12
- Flashing and window installation levels 9, 10 and 11
- Interior framing levels 10 and 11
- MEP rough-in levels 7, 8 and 9
- Drywall level 6
- Drywall taping and finishing level 5
- Wood doors, casing, trim level 4
- Painting level 3
- Ceramic tile level 3
- Sauna and Steam room install level 2

Coming Next Week

- Interior framing level 11 continues
- Drywall level 7
- Drywall taping and finishing level 6
- Wood doors and trim level 5
- Paint level 4
- Ceramic tile level 3 continues
- Casework level 3

<u>Current Crew Size</u>

Scope	Personnel
Vertical Concrete	16
Crane Operator	1
Electrical	21
Plumbing	24
HVAC Duct	12
Fire Sprinklers	7
Metal Stud Framing/Sheet Rock	62
Interior Paint	12
Interior Wood Trim	6
Weather Barrier	21
Window Installation	11
Ceramic Tile	7
Roofing	8
Sauna/Steam Rooms	2
Caseworkk	2
Stairs/Bump outs	3
	Vertical Concrete Crane Operator Electrical Plumbing HVAC Duct Fire Sprinklers Metal Stud Framing/Sheet Rock Interior Paint Interior Paint Interior Wood Trim Weather Barrier Window Installation Ceramic Tile Roofing Sauna/Steam Rooms Caseworkk



Aerial photo from Southeast



Overall Northwest elevation

Finished bedroom in mock-up unit



Hallway painting level 2





Metal siding in courtyard



Volleyball court on roof





Parapet roofing

View of Autzen Stadium from roof